



Current	30-100A
Duty Cycle	100A 60%
Gas	Air/N2
Gas Pressure	70-80 psi (4.8-5.5 bar)
Gas Flow	420 SCFH (240 lpm)
Pilot	Electrode (18-22A)
Combustion	Without High Frequency

Part Number	Product Code	Product Description
	1051900026	GeKaMac PT-105 Plasma Torch 6mt
	1052000022	GeKaMac PTM-105 Plus Automation Cutting Torch 6mt
1	6052000478	GeKaMac PT 105 Plasma Head
1b	6052000468	GeKaMac PT 105 Air Tube
3	6052000469	GeKaMac PT 105 Plasma Electrode
4	6052000470	GeKaMac PT 105 Gas Distributor 30-70A
5	6052000471	GeKaMac PT 105 Gas Distributor 30-70A
6	6052000472	GeKaMac PT 105 Plasma Nozzle 1.1mm (50-60A)
7	6052000473	GeKaMac PT 105 Plasma Nozzle 1.3mm 80A
7	6052000474	GeKaMac PT 105 Plasma Nozzle 1.5mm 100A
8	6052000477	GeKaMac PT 105 Plasma Nozzle
12	6052000475	GeKaMac PT 105 Plasma Distance Shield 100A
1a	6052000491	GeKaMac PTM 105 Plasma Head (Automation)
10	6052000492	GeKaMac PTM 105 Plasma Automation Shield 80-100A
9	6052000605	GeKaMac PTM 105 Plasma Automation Shield 30-70A
11	6052000604	GeKaMac PT 105 Compass Set

Compatible Machines: PoWerPlus+Cut 100