



Current	30-80A
Duty Cycle	80A 60%
Gas	Air
Gas Pressure	65-75 psi (4.4-5.0 bar)
Gas Flow	340 scfh (160 lpm)
Pilot	Electrode (18-22A)
Combustion	Without High Frequency

Part Number	Product Code	Product Description
	1051900027	GeKaMac PT80 Plasma Torch 6mt
5	1051900046	GeKaMac PT80 Plasma Torch 6mt (Automation)
1	6052000489	GeKaMac PT80 Plasma Head
1a	6052000455	GeKaMac PT80 Plasma Head (Automation)
2	6052000490	GeKaMac PT80-100 Plasma Handle(With Trigger)
1b	6052000480	GeKaMac PT80 Air Tube
3	6052000483	GeKaMac PT80 Plasma Electrode
4	6052000484	GeKaMac PT80 Gas Distributor
6	6052000485	GeKaMac PT80 Plasma Nozzle 1.0mm
6	6052000486	GeKaMac PT80 Plasma Nozzle 1.2mm
6	6052000487	GeKaMac PT80 Plasma Nozzle 1.3mm
7	6052000488	GeKaMac PT80 Plasma Nozzle
8	6052000481	GeKaMac PT80 Distance Foot (Double Foot)
22	6052000482	GeKaMac PT80 Compass Set

Compatible Machines: PoWerPlus+Cut 65